

Electrostatic Sensor

IZD10/IZE11 Series

- Potential measurement: ± 20 kV (detected at a 50 mm distance)
 ± 0.4 kV (detected at a 25 mm distance)
- Detects the electrostatic potential and outputs in an analog voltage.
 - Output voltage: 1 to 5 V (Output impedance: Approx. 100 Ω)



IZS

IZN

IZF

ZVB

IZD

IZE

IZH

The importance of the static electric control is put on confirming the “actual status”.

Broadens your coverage of electrostatic potential measurement applications!

Electrostatic sensor
IZD10 Series


- Output: Switch output x 2 + Analog output (1 to 5 V, 4 to 20 mA)
- Minimum unit setting: 0.001 kV (at ± 0.4 kV), 0.1 kV (at ± 20 kV)
- Display accuracy: $\pm 0.5\%$ F.S. ± 1 digit or less
- Detection distance correction function (adjustable in 1 mm increments)
- Supports two types of sensors (± 0.4 kV and ± 20 kV) through range selection

Electrostatic sensor monitor IZE11 Series



Electrostatic Sensor/IZD10 Series

Small and easy to mount



Electrostatic Sensor Monitor/IZE11 Series

2-color display (Red/Green)


Able to set the display color in 4 patterns.




| Pattern | ON | OFF |
|---------|-------|-------|
| (1) | Red | Green |
| (2) | Green | Red |
| (3) | Red | Red |
| (4) | Green | Green |

Mountable even with a sensor touched with each other

Possible to reduce panel fitting labor.



Connection by connector



Functions

- Detection distance correction
- Peak/Bottom value indication
- Keylock
- Zero-adjust
- Error display
- Switch output anti-chattering
- Selection of connection sensor

IZD10 Series


Technical Data

Output Signal


When measuring the potential of a charged object with an electrostatic sensor, the relationship between the electrostatic potential being measured and the output voltage varies depending on the sensor's installation distance. The relationship in the installation distance between the electrostatic sensor's output voltage and the detected electrostatic potential is as shown in the figure below: (The installation distance in the figure refers to the distance between the object being measured and the electrostatic sensor.)

Relationship in installation distance between electrostatic potential and sensor output voltage

IZD10-110





IZD10-510



Detection Range

The relationship between the electrostatic sensor's installation distance and the detection range is as follows:



IZD10-110

(Potential measurement: ± 0.4 kV)

| Installation distance (mm) | Detection range (mm) |
|----------------------------|----------------------|
| 10 | 45 |
| 20 | 85 |
| 25 | 100 |
| 30 | 120 |
| 40 | 150 |
| 50 | 180 |

IZD10-510

(Potential measurement: ± 20 kV)


| Installation distance (mm) | Detection range (mm) |
|----------------------------|----------------------|
| 25 | 100 |
| 30 | 120 |
| 40 | 150 |
| 50 | 180 |
| 60 | 205 |
| 70 | 225 |
| 75 | 235 |

Electrostatic Sensor

IZD10 Series



How to Order



Specifications

| Model | IZD10-110 | IZD10-510 |
|-------------------------------|---|--|
| Potential measurement | ±0.4 kV (at detection distance: 25 mm) ^{Note)} | ±20 kV (at detection distance: 50 mm) ^{Note)} |
| Output voltage | 1 to 5 V (Output impedance: Approx. 100 Ω) | |
| Effective detection distance | 10 to 50 mm | 25 to 75 mm |
| Linearity | ±5% F.S. (0 to 50°C, at detection distance: 25 mm) | ±5% F.S. (0 to 50°C, at detection distance: 50 mm) |
| Output delay time | 100 ms or less | |
| Power supply voltage | 21.6 to 26.4 VDC (Within 24 VDC ±10%) | |
| Current consumption | 40 mA or less | |
| Operating ambient temperature | 0 to 50°C | |
| Operating ambient humidity | 35 to 85% Rh (with no condensation) | |
| Material | Head case : ABS Amplifier case : ABS | |
| Vibration resistance | Durability 50 Hz Amplitude 1 mm X, Y, Z each 2 hours | |
| Shock resistance | 100 m/s ² | |
| Weight | 185 g (including cable weight) | |
| Compliance with EN standards | Protective class : Class III (EN60950-1) Pollution Degree 3 CE marking : Low voltage directive : 2006/95/EC Only when connected to a SELV-type external circuit. | |
| EMC directive | 2004/108/EC | |
| UL standards | UL508 | |


Note) The relationship between the measured potential and the output voltage varies depending on the detection distance.

For details on the relationship in the detection distance between the measured potential and the output voltage, refer to the graph in "Technical Data - Output Signal" on page 503.

Connection Circuit and Wiring Table

Connect the lead wires according to the following connection circuit and wiring table.

1. Connection circuit



2. Wiring table

| Lead wire color | Description | Function |
|-----------------|---------------|------------------------|
| Brown | DC (+) | Power supply 24 VDC |
| Blue | DC (-) | Power supply 0 V |
| White | Sensor output | Analog output 1 to 5 V |

Ground with
a resistance
value of 100 Ω
or less.

Warning

Always ground the electrostatic sensor.


Be sure to ground the GND terminal with a resistance value of 100 Ω or less. In addition, a dedicated power supply is recommended for use as the sensor-driving power supply. Connecting any equipment other than the sensor to this power supply may trigger the malfunctioning or breakdown of the equipment when static electricity is discharged to the sensor head or when noise enters the GND terminal.

Note) When using the cable on the external equipment connection side after cutting it short, do not connect a shielding wire (since the shielded line is wired in common with the amplifier case, provide a frame ground on the amplifier case side).

* Text in () refers to each lead wire coating color of the dedicated cable.

Dimensions

IZD10-110
IZD10-510



Electrostatic Sensor Monitor

IZE11 Series



How to Order

IZE11 0

Input/Output specifications

| | |
|---|--|
| 0 | NPN open collector 2 outputs + Analog output 1-5 V |
| 1 | NPN open collector 2 outputs + Analog output 4-20 mA |
| 2 | PNP open collector 2 outputs + Analog output 1-5 V |
| 3 | PNP open collector 2 outputs + Analog output 4-20 mA |

Option 1

| | |
|-----|---|
| Nil | None |
| L | <p>Connector cable for power supply/output</p> <p>Connector cable for power supply/output ZS-28-A</p> |

Note) The cable is not connected but packed together with product for shipment.

Option 3

| | |
|-----|--|
| Nil | None |
| C | <p>With connector for sensor connection</p> <p>Connector for sensor connection (e-con connector) ZS-28-C</p> |

Note) The connector is not connected but packed together with product for shipment.

Option 2

| | |
|-----|---|
| Nil | None |
| A | <p>Bracket</p> <p>Mounting screw (M3 x 5L)</p> <p>Bracket</p> |
| B | <p>Panel mount adapter</p> <p>Panel</p> <p>Panel mount adapter</p> <p>Mounting screw (M3 x 8L)</p> |
| D | <p>Panel mount adapter + Front protective cover</p> <p>Panel</p> <p>Front protective cover</p> <p>Panel mount adapter</p> <p>Mounting screw (M3 x 8L)</p> |

Note) The options are not attached but packed together with product for shipment.

Options/Part No.

| Description | Part no. | Note |
|---|----------|-----------------------|
| Connector cable for power supply / output (2 m) | ZS-28-A | |
| Bracket | ZS-28-B | With M3 x 5L (2 pcs.) |
| Connector for sensor connection | ZS-28-C | 1 pc. |
| Panel mount adapter | ZS-27-C | With M3 x 8L (2 pcs.) |
| Panel mount adapter + Front protective cover | ZS-27-D | With M3 x 8L (2 pcs.) |

Specifications

| Model | | IZE11□ | |
|---|--|---|-------------------------------------|
| Connection sensor | | IZD10-110 | IZD10-510 |
| Rated measurement range | | -0.4 kV to +0.4 kV ^{Note 1)} | -20 kV to +20 kV ^{Note 2)} |
| Min. unit setting | | 0.001 kV | 0.1 kV |
| Measurement distance setting | | 10 to 50 mm | 25 to 75 mm |
| Power supply voltage | | 21.6 to 26.4 VDC (24 VDC ±10% or less, with power supply polarity protection) | |
| Current consumption | | 50 mA or less (excluding sensor unit's current consumption) | |
| Sensor input | | 1 to 5 VDC (Input impedance: 1 MΩ) | |
| | Number of inputs | 1 input | |
| | Input protection | With excess voltage protection (up to 26.4 V) | |
| | Hysteresis | Hysteresis mode: Variable Window comparator mode: Variable | |
| Switch output | | NPN or PNP open collector: 2 outputs | |
| | Max. load current | 80 mA | |
| | Max. applied voltage | 30 VDC (with NPN output) | |
| | Residual voltage | 1 V or less (with load current of 80 mA) | |
| | Short circuit protection | With short circuit protection | |
| | Response time (including sensor response time) | 100 ms or less Response time with anti-chattering function: 500 ms, 1 s, 2 s or less | |
| | Voltage output | Output voltage: 1 to 5 V (with rated pressure range), Output impedance: Approx. 1 kΩ | |
| | Accuracy (for readings) (25°C) | ±1% F.S. | |
| Analog output | Current output | Output current: 4 to 20 mA (with rated pressure range) Max. load impedance: 600 Ω (at 24 VDC), Min. load impedance: 50 Ω | |
| | Accuracy (for readings) (25°C) | ±1% F.S. | |
| | Response time (including sensor response time) | 200 ms (without filter), 1.5 s (with filter) or less | |
| Display accuracy | | ±0.5% F.S. ±1 digit | |
| Display | | 3 + 1/2 digit, 7-segment indicator, 2-color display (Red/Green) Sampling cycle: 5 times/s | |
| Indicator light | | OUT1: Lights up when output is turned ON (Green), OUT2: Lights up when output is turned ON (Red). | |
| Environment | Enclosure | IP40 | |
| | Operating temperature range | Operating: 0 to 50°C, Stored: -10 to 60°C (with no freezing or condensation) | |
| | Operating humidity range | Operating/Stored: 35 to 85% RH (with no condensation) | |
| | Withstand voltage | 1000 VAC for 1 minute between terminals and housing | |
| | Insulation resistance | 50 MΩ or more (500 VDC measured via megohmmeter) between terminals and housing | |
| | Vibration resistance | 10 to 150 Hz at whichever is smaller of 1.5 mm amplitude or 98 m/s ² acceleration, in X, Y, Z direction for 2 hrs. each (De-energized) | |
| | Impact resistance | 100 m/s ² in X, Y, Z directions 3 times each (De-energized) | |
| Temperature characteristics | | ±0.5% F.S. (25°C reference) | |
| Connection method | | Power supply, Output connection: 5-pin connector, Sensor connection: 4-pin connector | |
| Material | | Front case: PBT, Rear case: PBT | |
| Weight (excluding power supply/output connection cable) | | 30 g | |
| Standards | | CE marking, UL (CSA) compliant | |

Note 1) Rated value when the distance between the charged object and the sensor is 25 mm

Note 2) Rated value when the distance between the charged object and the sensor is 50 mm

IZS

IZN

IZF

ZVB

IZD

IZE

IZH

IZE11 Series

Example of Internal Circuit and Wiring


Output specifications

The wire colors (brown, black, white, gray and blue) shown in the circuit diagram apply when SMC's power supply and output connection cable (Part no.: ZS-28-A) are used.

IZE110

NPN open collector output: 2 outputs
Max. 30 V, 80 mA
Residual voltage 1 V or less


Analog output: 1 to 5 V
Output impedance: Approx. 1 k Ω



IZE112

PNP open collector output: 2 outputs
Max. 80 mA
Residual voltage 1 V or less


Analog output: 1 to 5 V
Output impedance: Approx. 1 k Ω



IZE111

NPN open collector output: 2 outputs
Max. 30 V, 80 mA
Residual voltage 1 V or less


Analog output: 4 to 20 mA
Max. load impedance: 600 Ω (24 VDC)
Min. load impedance: 50 Ω



IZE113

PNP open collector output: 2 outputs
Max. 80 mA
Residual voltage 1 V or less

Analog output: 4 to 20 mA
Max. load impedance: 600 Ω (24 VDC)
Min. load impedance: 50 Ω



Description

LCD display


Shows the current electrostatic potential, set mode, and error code. Four display methods are available for selection, including an option for always displaying in a single color, red or green, and an option for switching from green to red in conjunction with the output.

Output (OUT1) display (Green)

Turns on when the OUT1 output is on.

▲ button

Use this button to change the mode or increase the ON/OFF set value. It also allows you to switch to the peak value display mode.



Output (OUT2) display (Red)

Turns on when the OUT2 output is on.


SET button

Use this button to switch the mode and set the set value.


▼ button

Use this button to change the mode or decrease the ON/OFF set value. It also allows you to switch to the bottom value display mode.

Dimensions




Connection cable for power supply/output (ZS-28-A)




Connector for sensor connection

| Pin no. | Terminal name |
|---------|---------------|
| 1 | DC (+) |
| 2 | N.C. |
| 3 | DC (-) |
| 4 | IN (1 to 5 V) |


With bracket



With panel mount adapter




With panel mount adapter + Front protective cover




Dimensions

Panel fitting dimensions * Panel thickness: 0.5 to 6 mm



Note) When providing a curvature radius (R), keep it to R2 or smaller.



Function Details

A Detection range correction function

By previously inputting a distance from the sensor to the object being measured, it is possible to reduce errors due to variations in the measurement distance.

B Peak/Bottom value indication

This function constantly detects and updates the maximum and minimum pressure values and allows to hold the display value.

C Keylock function

This function prevents incorrect operations such as changing the set value accidentally.

D Zero-adjust function

The reading of the measured voltage can be adjusted to zero. The reading can be corrected within $\pm 10\%$ of F.S. from the factory-set condition.

E Error display function

| Error description | Error display | Condition |
|-------------------------|--------------------|---|
| Over-current error | OUT1 Er1 | Load current of switch output is more than 80 mA. |
| | OUT2 Er2 | |
| System error | Er3 | Internal data error |
| Zero-adjust error | Er4 | During zero adjustment, an amount of static electricity beyond $\pm 10\%$ of F.S. has been given to the sensor. * After displaying the error code for approximately one second, the sensor automatically returns to measurement mode. The zero point may slightly fluctuate depending on the individual product difference and the sensor's mounting condition during zero adjustment. |
| Over-flow Under-flow | HHH | The displayable range has been exceeded because an amount of static electricity beyond the upper limit of the voltage measurement range has been given to the sensor or the measurement distance setting and/or the sensor mounting position is inappropriate, or for other reasons. |
| | LLL | The sensor may not have been wired yet or may have mistakenly wired. Alternatively, the displayable range has been exceeded because an amount of static electricity beyond the upper limit of the voltage measurement range has been given to the sensor or the measurement distance setting and/or the sensor mounting position is inappropriate, or for other reasons. |


F Anti-chattering function

The charged voltage may vary temporarily. This function prevents such a momentary change from being detected as an abnormal voltage by changing the response time setting.

Response time: 100 ms, 500 ms, 1 s, 2 s or less

(Principal)

When a measured value is retained for an optionally set time length (delay time), the sensor compares the measured value with the setpoint to provide a switched output.



G Connection sensor selection function

The type (range) of electrostatic sensor to be connected can be selected. The monitor is factory-set to the ± 0.4 kV option.



Iزد10 Series Electrostatic Sensors Precautions 1

Be sure to read this before handling the products.

Refer to back page 50 for Safety Instructions and pages 514 and 515 for Specific Product Precautions.

Selection

Warning

1. **This product is intended to be used with general factory automation (FA) equipment.**

If considering using the product for other applications (especially those stipulated in 4 on back page 50), consult with SMC beforehand.

2. **Use this product within the specified voltage and temperature range.**

Using outside of the specified voltage can cause a malfunction, damage, electrical shock, or fire.

3. **This product is not explosion-protected.**

Never use this product in environment, where dust explosion may occur or flammable or explosive gases are used. This can cause fire.

Caution

1. **This product is not cleaned. Before bringing this product into a clean room, remove particles using the clean dry air blow, etc. Before using the product, confirm that its cleanliness satisfies the required level.**
2. **Do not blow the clean dry air to the detection hole. Otherwise, the detection mechanism may be deformed. This may cause not only incorrect detection of the charged electric potential, but also sensor failure.**

Mounting

Warning

1. **Reserve an enough space for maintenance, piping and wiring.**

Please take into consideration that the port location for external equipment, need enough space for the cable to be easily attached/detached.

To avoid excessive stress on the port location for external equipment, cable entry for sensor head and mounting base of cable entry for amplifier, please take into consideration the cables minimum bending radius and avoid bending at acute angles.

Wiring with excessive twisting, bending, etc. can cause a malfunction, wire breakage, fire or air leakage.

Minimum bending radius: Sensor cable 25 mm
(Note: Shown above is wiring with the fixed minimum allowable bending radius and at a temperature of 20°C. If used under this temperature, the port location for external equipment, cable entry for sensor head and mounting base of cable entry for amplifier can receive excessive stress even though the minimum bending radius is allowable.)

2. **Mounting on a plane surface.**

If there are irregularities, cracks or height differences, excessive stress will be applied to the frame or case, resulting in damage or other trouble. Also, do not drop or apply a strong shock. Otherwise, damage or an accident can occur.

3. **Do not drop or bump the sensor.**

When handling the sensor, do not drop the sensor or apply strong impact to it, as this may cause the sensor to malfunction or break down.

4. **Do not use this product in an area where noise (electric magnetic field or surge voltage, etc.) are generated.**

Using the ionizer under such conditions may cause it to malfunction or internal devices to deteriorate or break down. Take noise countermeasures and prevent the lines from mixing or coming into contact with each other.

Mounting

Warning

5. **Observe the tightening torque requirements when installing the ionizer. (Refer to the operation manual included with the product.)**

If overtightened with a high torque, the mounting screws or mounting brackets may break. Also, if under tightened with a low torque, the connection may loosen.

6. **Do not directly touch the detection surface of the sensor head with a metal piece or hand tool.**

Touching the surface in this manner may not only cause the sensor to not only fail to provide the specified functionality and/or performance but also result in a sensor failure or an accident.

7. **Do not affix any tape or seals to the main unit.**

If the tape or seal contains any conductive adhesive or reflective paint, a dielectric phenomenon may occur due to ions arising from such substances, resulting in electrostatic charging or electric leakage.

8. **Installation and adjustment should be conducted after turning off the power supply.**


9. **Keep the installation distance long enough to prevent static electricity from being discharged through the sensor head (refer to Technical Data on page 503 and Specifications on page 504).**

Static electricity may be discharged through the sensor head depending on the electrostatic potential of the object. Be extremely careful about this since electrostatic discharge through the sensor head may cause the sensor to break down.

Caution

1. **Install the electrostatic sensor away from walls, etc., as shown below:**

The ionizer may fail to measure electrostatic potentials correctly if a wall or other obstacles exist within the clearances shown in the following figure.



(mm)

| A | B |
|----|-----|
| 10 | 20 |
| 20 | 40 |
| 25 | 45 |
| 30 | 55 |
| 40 | 65 |
| 50 | 75 |
| 60 | 90 |
| 70 | 100 |
| 75 | 105 |

2. **After installation, always make sure that the electrostatic potential is measured correctly.**

Errors may occur in the detected electrostatic potential depending on the ambient installation conditions, etc. After installation, check the sensor's condition with regard to electrostatic potential detection.



IZD10 Series

Electrostatic Sensors Precautions 2

Be sure to read this before handling the products.

Refer to back page 50 for Safety Instructions and pages 514 and 515 for Specific Product Precautions.

Wiring/Piping

Warning

1. Before wiring confirm if the power supply voltage is enough and that it is within the specifications before wiring.
2. To maintain the product performance, ground the FG terminal with a resistance value of 100 Ω or less while referring to the instructions stated in this document. When using a commercially available switching regulator, ground the GND and FG terminals.
3. When applying the power supply, pay special attention to the wiring and/or surrounding environment until the safety is confirmed.
4. Do not remove or attach wires from/to any parts, including the power supply, while the sensor is turned on, as this may cause the surface electrostatic sensor to malfunction. Be sure to the sensor is turned off prior to performing any wiring (including plugging/unplugging connectors).
5. If the power line and high pressure line are routed together, this product may malfunction due to noise. Therefore, use a separate wiring route for this product.
6. Be sure to confirm there are no wiring errors before starting this product.
Faulty wiring will lead to product damage or malfunction.
Applying 24 VDC to the sensor output will directly lead to internal circuitry breakdown.

Operating Environment/Storage Environment

Warning

1. Operate at an ambient temperature that is within the specifications.
Ambient temperature ranges from 0 to 50°C. Do not use the sensor in locations where the temperature may change suddenly even if the ambient temperature range is within the specified limits, resulting in condensation.
2. Environments to avoid
Avoid using and storing this product in the following environments since they may cause damage to this product.
 - a) Avoid using in a place that exceeds an ambient temperature range of 0 to 50°C.
 - b) Avoid using in a place that exceeds an ambient humidity range of 35 to 85% Rh.
 - c) Avoid using in a place where condensation occurs due to a drastic temperature change.
 - d) Avoid using in a place in the presence of corrosive or explosive gas or where there is a volatile combustible.
 - e) Avoid using in an atmosphere where there are particles, conductive iron powders, oil mist, salt, solvent, blown dust, cutting oil (water, liquid), etc.
 - f) Avoid using in direct sunlight or radiated heat.
 - g) Avoid using in a place where there is a strong magnetic noise (strong electric field, strong magnetic field, or surge).
 - h) Avoid using in a place where the main body is electro-statically discharged.
 - i) Avoid using in a place where a strong high frequency occurs.
 - j) Avoid using in a place where this product is likely to be damaged by lightning.
 - k) Avoid using in a place where direct vibration or shock is applied to the main body.
 - l) Avoid using in a place where there is a force large enough to deform this product or weight is applied to the product.

Operating Environment/Storage Environment

Warning

3. The electrostatic sensor is not resistant to lightning surges.
Take measures for protection against lightning surges on the system side.

Maintenance

Caution

1. Periodically inspect the electrostatic sensor to check if it is operated while being out of order.
Only a person having an adequate knowledge and experience about the system is allowed to inspect the sensor.
2. Do not disassemble or rebuild this product.
Otherwise, an electrical shock, damage and/or a fire may occur. Also, the disassembled or rebuilt products may not achieve the performances guaranteed in the specifications, and exercise caution because the product will not be warranted.

Handling

Warning

1. Do not drop, bump or apply excessive impact (100 m/s² or more) while handling.
Even though it does not appear to be damaged, the internal parts may be damaged and cause a malfunction.
2. Do not operate this product with wet hands. Otherwise, an electrical shock or accident may occur.
3. Before use, allow the sensor to warm up for 10 minutes or more after power-on.
The sensor may provide unsteady readings immediately after power-on.
4. Use a UL-approved DC power supply compatible with the UL1310 Class 2 Power Unit or with power units comprising a UL1585 Class 2-compliant transformer, in combination with the sensor.

IZS

IZN

IZF

ZVB

IZD

IZE

IZH



Iزد10 SeriesSpecific Product Precautions 1

Be sure to read this before handling the products.

Refer to back page 50 for Safety Instructions and pages 512 and 513 for Electrostatic Sensors Precautions.

Mounting of Electrostatic Sensor

Mounting of Sensor Head


1. When using the electrostatic sensor, install it in a location where the detection hole of the sensor head can detect the object being measured. (Refer to "Technical Data – Detection Range" on page 503.)

2. Install the sensor so that the distance between the detection hole and the object's surface is within 10 to 50 mm when the Iزد10-110 is used and within 25 to 75 mm when the Iزد10-510 is used. Be careful not to allow the sensor head to come into contact with the object. Static electricity may be discharged through the sensor head depending on the electrostatic potential of the object. Keep the installation distance long enough to prevent static electricity from being discharged through the sensor head. Be very careful about this since electrostatic discharge through the sensor head may cause the sensor to break down.

The detection range and the sensor output vary depending on the installation distance. For more information, refer to "Technical Data - Output Signal and - Detection Range" on page 503.


3. Use two M3-size screws (should be prepared separately) to mount the sensor head.

Recommended tightening torque for M3 screws: 0.61 to 0.63 N·m



4. Align bolts with their seating surfaces to mount the sensor head. Mounting it by inserting the bolts from the opposite side may damage the sensor head.

The sensor head enclosure is in common with the GND terminal for reasons of the sensor structure. When installing or turning on the sensor, be very careful to avoid the enclosure from being short-circuited to the +24 V power supply. The detection hole is opened in order to detect static electricity. If any foreign matters enter the hole or the inner part of the hole is touched with a hand tool, etc., the sensor may malfunction or break down, resulting in a failure to correctly detect static electricity. Be careful not to allow any foreign matters to enter the inner part or touch it with a hand tool, etc. Do not pull the cable extending from the sensor head or twist it at the head's neck. Forcibly pulling or twisting the cable in this manner may cause the sensor head and/or the cable to break down.



Mounting of Sensor Amplifier

1. Use two M3-size screws (should be prepared separately) to mount the sensor amplifier.

Recommended tightening torque for M3 screws: 0.61 to 0.63 N·m

2. Align bolts with their seating surfaces to mount the sensor amplifier.


Mounting it by inserting the bolts from the opposite side may damage the sensor amplifier.

3. Do not pull the cable extending from the sensor amplifier or twist it at the amplifier's neck.

Forcibly pulling or twisting the cable in this manner may cause the sensor amplifier and/or the cable to break down.

4. Be sure to ground the FG terminal with a resistance value of 100 Ω or less since the sensor amplifier case is common to the FG terminal.

Recommended crimping terminal: TMEN1.25-3 insulation-coated crimping terminal from NICHIFU Co., Ltd.





IZE11 Series Electrostatic Sensor Monitors Precautions

Be sure to read this before handling the products. Refer to back page 50 for Safety Instructions.

■ Electrostatic Sensor Monitor

Operating Environment

⚠ Warning


1. Our electrostatic sensor monitor are CE marked; however, they are not equipped with surge protection against lightning. Lightning surge countermeasures should be applied directly to system components as necessary.
2. Our electrostatic sensor monitor do not have an explosion proof rating. Never use in the presence of an explosive gas as this may cause a serious explosion.

Mounting

⚠ Caution


1. Mounting with a bracket

Mount a bracket to the body using two M3 x 5L mounting screws. Tightening torque for bracket mounting screw should be 0.5 to 0.7 N·m.



2. Mounting with panel mount adapter


Mount a panel mount adapter using two M3 x 8L mounting screws.



3. When removing the panel mount adapter

To remove the electrostatic sensor monitor with a panel mount adapter from user equipment, first remove the two mounting screws, then push the clips outward as shown in the figure and pull the monitor back towards you.

Removing the monitor otherwise may damage the monitor and/or the panel mount adapter.




Wiring

⚠ Caution


1. Connection/Removal of Connector

- Insert the connector straight while pinching the lever, and then push the lever into the jack of the housing and lock it.
- Pull the connector straight out while applying pressure with your thumb to the lever and unhooking it from the jack.



2. Connector pin no. of connection cable for power supply/output

DC (+) Brown 5
OUT1 Black 4
OUT2 White 3
Analog Gray 2
DC (-) Blue 1



Setting

⚠ Warning

1. If not correctly set to the option specified for the connected sensor, the monitor will fail to display correct electrostatic potentials.

When initially setting up the monitor or connecting a sensor to the monitor, always make sure that the selected option and the electrostatic sensor agree with each other.

* The monitor is factory-set to the ± 0.4 kV option.